


Main Building sits perpendicular to Main Street, and consequently does not have exposure.



New drive thru leads traffic to the rear of the shopping center and adds exposure to these businesses.